



## **SB, YT Tractors & RZT Zero Turn Riders equipped with 48" ClearCut Decks, YT2348F, YT2448F, RZT48X & RZT 48, 2019-06**

### **Affected models**

Model	PNC	Serial Range	
		Start	End
YT2348F	960430237	110317A001001	080218A099999
YT2448F	960430293	122018A001001	061219A099999
RZT48X	967671001	102918B001001	042519B099999
RZT 48	967672001	090617C001001	061319C099999

### **Affected markets**

All.

### **Description**

Some customers are reporting an uncut strip of grass after mowing. The uncut strip is usually near the center of the cut. If this condition is present, install bolt-on baffle kit PN 596693501.

### **Action**

	Product sold to end user	Residual inventory not yet sold
What is required:	Service is required	Service is not approved
When to do:	Only if encountered	Not required
What to do:	Install 48" ClearCut Bolt-on Baffle Kit PN 596693501	
How to do:	See instructions in kit 596693501	

### **Parts information**

New part no.	Part description	Quantity	Old part no.
596693501	48" ClearCut bolt On Baffle Kit	1	N/A

### **Warranty reporting information**

Normal warranty rules apply. A warranty claim must be filed for each unit serviced, even if service is labor only. Please include full serial number. All claims must be sent through our warranty process using only the information listed below:



**Service Bulletin**  
**B2190002A-15**

Action required

Information only

<b>Field</b>	<b>Selection or Entry</b>
Claim type (inventory)	Non required
Claim type (end users)	1 - Warranty
Failure description	SB B2190002A-15
Component code	602 Brackets / Support
Defect code	92 Part exchanged on request by Husqvarna
Labor allowance	30 units (3 hours)

**Revision History**

<b>Rev.</b>	<b>Date</b>	<b>Order id.</b>	<b>Description</b>
A	2019-06	SB-4495	Created